

VCDS-Lite
Windows Based VAG/VAS Emulator
Version: Release 1.2
www.Ross-Tech.com

Workshop Code: 000 00000

Diagnostic Trouble Code Report
Saturday, 08 April 2023, 13:37:10:4863

VIN Number: License Plate:
Mileage: Repair Order:

Control Module Part Number: 036 906 013 F
Component and/or Version: MED7.5.11 4628
Software Coding: 00051
Additional Info: WAUZZZ8Z03N026882 AUZ7Z0B2288224

4 Faults Found:

- 17415 - Torque Difference Cylinder 4: Limit Value Exceeded
P1007 - 35-00 - -
- 16684 - Random/Multiple Cylinder Misfire Detected
P0300 - 35-00 - -
- 16688 - Cylinder 4: Misfire Detected
P0304 - 35-00 - -
- 18043 - Powertrain Data Bus: Missing Message from A/C Controller
P1635 - 35-10 - - - Intermittent

Readiness: 0000 0000