VCDS
Windows Based VAG/VAS Emulator Running on Windows 7 x86
VCDS Version: Release 22.10.0  Data version: 20221026 DS344.0
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000 000000

Self-Diagnosis Log
Tuesday,21,March,2023,07:46:56:31251

VIN: WAUZZZ8Z42N  License Plate:
Mileage:  Repair Order:

Chassis Type: 8Z (8Z - Audi A2 (2000 > 2005))
Scan: 01 02 03 08 15 16 17 18 37 45 46 56 57 75 76 77

VIN: WAUZZZ8Z42N033297

---

Address 01: Engine  Labels: 036-906-034-APE.lbl
Part No: 036 906 034 EG
Component: MARELLI 4MV G  4030
Coding: 00051
Shop #: WSC 02154
VCID: 5BE09DDBAA3221E3DE0-4B5C
WAUZZZ8Z42N033297  AUZ7Z0B2040113

No fault code found.
Readiness: 0010 0001

---

Address 03: ABS Brakes  Labels: 8Z0-907-379-MK60.lbl
Part No: 8Z0 907 379 C
Component: ESP FRONT MK60  0101
Coding: 0019463
Shop #: WSC 02154 785 00200
VCID: 48CA52970EA45A7B632-5184

1 Fault Found:
00778 - Steering Angle Sensor (G85)
014 - Defective - Intermittent

---

Address 08: Auto HVAC  Labels: None
Part No: 8Z2 820 043
Component: A2-KLIMAVOLLAUTOMAT 0406
VCID: 75B4EB632CD69793C84-258E

2 Faults Found:
01272 - Positioning Motor for Central Flap (V70)
41-10 - Blocked or No Voltage - Intermittent
00818 - Sensor for Evaporator Outlet Temperature (G263)
30-00 - Open or Short to Plus

---