

Anti-Theft Coding

This unit is equipped with security coding which prevents it from being reactivated by unauthorised persons following its removal from the vehicle.

Every time

- the unit is disconnected from the vehicle's power supply
- the battery is disconnected
- the radio's fuse has blown

the message "SAFE" will appear on the display when the unit is switched on. The unit can only be reactivated when the **correct** code has been entered.

This code number is stuck on the "Equipment Card" along with the serial number at the front of the manual, under the table of contents.

Be sure to remove the "Equipment Card" from the manual and keep it in a safe place - do not leave it in the vehicle. The unit is only then truly useless to thieves!



Removing the electronic block

The electronic block can be removed if the **correct** code number is entered.

The following steps must be performed in the correct order:

- Switch on the system - after the Audi start screen appears, you will see the menu for entering the code along with the message: "Please enter your numerical code".

- To enter the code number mark the digits one by one using the rotary/pushbutton (21) and press to confirm each digit.

The digits will be entered in the number input fields below.

- Use the rotary/pushbutton (21) to mark "OK" and press it to confirm your entry.

The unit is ready for operation again!

Incorrect code number

If you enter an incorrect code number while attempting to remove the electronic block, the message "SAFE" will flash on the screen, followed by the incorrect code number. The following message will appear under the digit input fields: "1. Code-Eingabe falsch!"

The whole procedure can now be repeated **once**.

Should you enter the code number incorrectly again, the set will remain blocked for approx. 1 hour, i.e. it cannot be put into operation. After one hour - the unit must remain switched on and the key must be in the ignition - the number of attempts will have disappeared from the display and the electronic block can again be removed as described above.

The cycle - two attempts, one hour blocked - will continue to apply.

Note

If you have lost the radio card bearing the code number, please contact an Audi dealership.