

VCDS-Lite Version: Release 1.2

Thursday, 10 March 2022, 12:39:44:0

Chassis Type: 8Z - Audi A2

Scan: 01,02,03,08,15,16,17,18,37,45,46,56,57,75,76,77

---

Address 01: Engine            Labels: 036-906-034-APE.LBL

Controller: 036 906 034 Q

Component: MARELLI 4LV            3720

Coding: 00051

Shop #: WSC 02138

VCID: 20336383B3DB

WAUZZZ8ZZ1N051799            AUZ7Z0A1835314

2 Faults Found:

18057 - Powertrain Data Bus: Missing Message from ABS Controller

P1649 - 35-00 - -

17589 - Linear O2 Sensor; Reference Voltage: Open Circuit

P1181 - 35-10 - - - Intermittent

Readiness: 1010 0001

---

Address 03: ABS Brakes            Labels: None

Controller: 8Z0 907 379 B

Component: ESP            20            CAN    V015

Coding: 10758

Shop #: WSC 00000

VCID: 47E1D81F76B5

2 Faults Found:

65535 - Internal Control Module Memory Error

00-00 - -

00778 - Steering Angle Sensor (G85)

49-00 - No Communications

---

Address 08: Auto HVAC      Labels: None

Controller: 8Z2 820 043

Component: A2-KLIMAVOLLAUTOMAT 0406

VCID: F59DE2D7DCD9

No fault code found.

---

Address 15: Airbags      Labels: 8Z0-959-655.LBL

Controller: 8Z0 959 655 E

Component: Airbag Front+Seite 5005

Coding: 00102

Shop #: WSC 02152

VCID: 4EEFED3B99CF

No fault code found.

---

Address 17: Instruments                      Labels: 8Z0-920-xxx-17.LBL

Controller: 8Z0 920 950 A

Component: W1-KOMBIINSTR. VDO D13

Coding: 05442

Shop #: WSC 00258

VCID: 3C0BB7F33F73

WAUZZZ8ZZ1N051799                      AUZ7Z0A1835314

No fault code found.

---

Address 45: Inter. Monitor                      Labels: 8E0-951-177.LBL

Controller: 8Z0 951 177

Component: Innenraumueberw.                      D04

Coding: 00001

Shop #: WSC 00000

VCID: 55DD0257BC19

No fault code found.

---

Address 46: Central Conv.                      Labels: None

Controller: 8Z0 959 433 F

Component: Komfortgerät T1D                      03B3

Coding: 06858

Shop #: WSC 02138

VCID: 49E5DE2760A1

5 Faults Found:

01561 - Left Rear Door

59-10 - Can't Unlock - Intermittent

01562 - Right Rear Door

59-10 - Can't Unlock - Intermittent

01562 - Right Rear Door

61-10 - Won't De-Safe - Intermittent

01559 - Drivers Door

61-00 - Won't De-Safe

01560 - Passenger Door

61-00 - Won't De-Safe

---

Address 56: Radio

Labels: 8D0-035-1xx-56.LBL

Controller: 4B0 035 152 B

Component: Radio 0001

Coding: 00501

Shop #: WSC 02138

VCID: 18434B636B8B

1 Fault Found:

00852 - Loudspeaker(s); Front

36-10 - Open Circuit - Intermittent

End

---